

**Appendix F**  
**Spring and Fall 2006 Field Survey**  
**Photographs**

**Upper Trabuco Creek  
Spring Survey**



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 1

Description: Upper Trabuco Creek - Holy Jim area, cut bank near cabin on left bank

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 2

Description: Upper Trabuco Creek -beginning of braided channel

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 3

Description: Upper Trabuco Creek -man made dam; near cabin with big yellow water tank

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 4

Description: Upper Trabuco Creek -man made dam; near cabin with big yellow water tank

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 5

Description: Upper Trabuco Creek - boulders forming the dam near the cabin with the yellow water tank; note fencing used to retain borders

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 6

Description: Upper Trabuco Creek - fencing used to retain boulders on left bank; near yellow water tank

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 7

Description: Upper Trabuco Creek - repelling rope (purpose?); left bank

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.:8

Description: Upper Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 9

Description: Upper Trabuco Creek - mating newts

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 10

Description: Upper Trabuco Creek- assessing man made barrier near cabin with yellow water tank

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 11

Description: Upper Trabuco Creek - male newt

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 12

Description: Upper Trabuco Creek-top of the segment; begin under  
boulder flow

Date: 4/30/06





**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 13

Description: Upper Trabuco Creek - under boulder flow

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 14

Description: Upper Trabuco Creek - end of reach, looking upstream

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 15

Description: Upper Trabuco Creek - end of reach, looking downstream

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 16

Description: Upper Trabuco Creek - beginning of reach, looking downstream

Date: 4/30/06



**CDM**

**San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan**

Project No. **Spring Survey**

Photograph No.: **16**

Description: **Upper Trabuco Creek - beginning of reach, looking  
upstream**

Date: **4/30/06**

**Middle Trabuco Creek  
Spring Survey**



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.:1

Description: Middle Trabuco Creek

Date: 4/29/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 2

Description: Middle Trabuco Creek

Date: 4/29/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 3

Description: Middle Trabuco Creek

Date: 4/29/06



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 4

Description: Middle Trabuco Creek

Date: 4/29/06



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. **Spring Survey**

Photograph No.: 5

Description: **Middle Trabuco Creek**

Date: **4/29/06**



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. **Spring Survey**

Photograph No.: 6

Description: **Middle Trabuco Creek**

Date: **4/29/06**



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 7

Description: Middle Trabuco Creek

Date: 4/29/06



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 8

Description: Middle Trabuco Creek

Date: 4/29/06





**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 9

Description: Middle Trabuco Creek

Date: 4/29/06



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 10

Description: Middle Trabuco Creek- arundo thicket at beginning of  
segment

Date: 4/29/06



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 11

Description: Middle Trabuco Creek - collecting water quality data and velocity measurements at beginning of segment

Date: 4/29/06



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 12

Description: Middle Trabuco Creek - dense arundo thicket; roughly midway up segment on right bank

Date: 4/29/06



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 13

Description: Middle Trabuco Creek - typical view of segment; slow moving rifle. Note thick arundo thicket on right bank

Date: 4/29/06



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 14

Description: Middle Trabuco Creek - note mudstone of right bank. Mudstone outcrops began about 1/2 to 2/3 of the way up the segment.

Date: 4/29/06



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 15

Description: Middle Trabuco Creek - salt cedar (invasive); right bank over mineral seep/spring

Date: 4/29/06



**CDM**

San Juan and Trabuco Creeks Watershed  
Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.:16

Description: Middle Trabuco Creek - deer skeleton; near arundo thicket on right bank

Date: 4/29/06

**Lower Trabuco Creek  
Spring Survey**



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 1

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 2

Description: Lower Trabuco Creek-

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 3

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 4

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 5

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 6

Description: Lower Trabuco Creek

Date: 4/30/06





**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 7

Description: Lower Trabuco Creek- arundo stand

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.:8

Description: Lower Trabuco Creek- arundo thicket

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 9

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 10

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 11

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 12

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 13

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 14

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 15

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 16

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 17

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 18

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 19

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 20

Description: Lower Trabuco Creek - bullfrog caught in flatwater pond

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 21

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 22

Description: Lower Trabuco Creek -

Date: 4/30/06





**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 23

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 24

Description: Lower Trabuco Creek -typical wide, deep flatwater ponds

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. **Spring Survey**

Photograph No.: **25**

Description: **Lower San Juan Creek**

Date: **4/30/06**



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. **Spring Survey**

Photograph No.: **26**

Description: **Lower Trabuco Creek**

Date: **4/30/06**



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 27

Description: Lower Trabuco Creek

Date: 4/30/06



**CDM**

San Juan and Trabuco Creeks  
Watershed Steelhead Recovery Plan

Project No. Spring Survey

Photograph No.: 28

Description: Lower Trabuco Creek

Date: 4/30/06